DEKRA

VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA	LOCALITA'
30/06/2026	AUTOADRIA DIVISIONE OFFICINE SRL , Via Val Tiberina 140, 63074, SAN BENEDETTO DEL TRONTO (AP)

VEICOLO (MARCA - MODELLO - VERSIONE)	TARGA	TELAIO	1^ IMMATRICOLAZ.
SKODA OCTAVIA WAGON 2.0 TDI EVO 110KW SCOUT DSG 4WD SW 5-door (Euro 6D)	GK687FX	TMBLJ8NX8NY096628	17/05/2022

KM.	COLORE.	TIPO SMALTO
240559	Bianco Magnolia	PASTELLO/MONO

CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
	presa in carico									0,01		0,01
	#PRM# Disco ruota anteriore sx danneggiato											
	#PRM# Disco ruota anteriore dx danneggiato											
	#PRM# Disco ruota posteriore sx danneggiato											
	#PRM# Disco ruota posteriore dx danneggiato											
	#PRM# Parabrezza											
1981	Paraurti ant.	M	0,90	M		M	3,00					
1981	Scomposizione paraurti		1,60									
3040	Spoiler paraurti ant. P/Sportline nero perlato	S		S		S				194,86	S17	161,73
0556	#PRM# Cofano ant.											
1992	#PRM# Paraurti post.											
2209	Portello post.	M	0,90	M	1,30	M	2,70					
5322	Pannello int. portello post. nero	S		S		S				64,98	S17	53,93
5062	Scritta post. casa cromo	S		S		S				30,61	S17	25,41
3491	Coprivite braccio tergilunotto	S		S		S				5,88	S17	4,88
1621	#PRM# Modanatura sottoporta P/Scout nero satinato DX											
0362	Calotta retrovisore est. primer DX	M		M		M	0,50					
1945	#PRM# Parafango post. DX											
	TAPPETINO	S		S		S				50,00	S17	41,50

TOTALE TEMPI	SR	LA	VE	ME	TOTALE RICAMBI
	3,40	1,30	6,20	0,00	287,46

ORE SUPPLEMENTO DOPPIO STRATO 15 %	ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE	ORE AGGIUNTIVE PER VERNICIATURA	TOTALE ORE SUPPLEMENTARI	TOTALE ORE VERNICIATURA
0,93	0,71	1,60	3,24	9,44

NOTE

Pneumatico ant dx - Goodyear - 225/45/18 - estivo - 5 mm
Pneumatico ant sx - Goodyear - 225/45/18 - estivo - 5 mm
Pneumatico post dx - Goodyear - 225/45/18 - estivo - 5 mm
Pneumatico post sx - Goodyear - 225/45/18 - estivo - 5 mm
Pneumatico scorta - Kumho - 205/60/16 - estivo - 6 mm
Revisione in scadenza nel mese, CDC copia conforme, Periziato con tempo sereno

RICAMBI	287,46
MATER. DI CONSUMO ORE 9,44 €/ORA 12,00	113,28
USO DIME	0,00
SMALTIMENTO RIFIUTI	12,44
MANODOPERA CARR. ORE 14,14 €/ORA 45,00	636,30
MANODOPERA MECC. ORE 0,00 €/ORA 45,00	0,00
IMPONIBILE	1049,48
IVA	230,89
TOTALE COMPLESSIVO	1280,37

CODICE PERITO	FIRMA	RUOLO N.	FERMO TECNICO GIORNI	FOGLIO
176		0000	2	1

Legenda
FF:Forfait PRM:Promemoria DE:Difetto esecuzione GR:Grandine MAC:Macchiato NU:Normale usura SRG:Adesivi

DEKRA

VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE	LOCATION'
30/06/2026	AUTOADRIA DIVISIONE OFFICINE SRL , Via Val Tiberina 140, 63074, SAN BENEDETTO DEL TRONTO (AP)

VEHICLE (BRAND - MODEL - VERSION)	PLATE	CHASSIS	1st REGISTRATION.
SKODA OCTAVIA WAGON 2.0 TDI EVO 110KW SCOUT DSG 4WD SW 5-door (Euro 6D)	GK687FX	TMBLJ8NX8NY096628	17/05/2022

KM.	COLOR.	ENAMEL TYPE
240559	Bianco magnolia	Pastello/mono

PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff	TIME	Diff.	TIME	Diff.	TIME			
	Taking charge									0,01		0,01
	#PRM# Left front wheel damaged											
	#PRM# Right front wheel damaged											
	#PRM# Left rear wheel damaged											
	#PRM# Right rear wheel damaged											
	#PRM# Windscreen											
1981	Front bumper	M	0,90	M		M	3,00					
1981	Bumper dismantling		1,60									
3040	Spoiler bumper front p/sportline nero perlato	S		S		S				194,86	S17	161,73
0556	#PRM# Front lid											
1992	#PRM# Rear bumper											
2209	Tailgate	M	0,90	M	1,30	M	2,70					
5322	Pannello int. hatch rear nero	S		S		S				64,98	S17	53,93
5062	Written rear home cromo	S		S		S				30,61	S17	25,41
3491	Rear screen wiper arm screw cover	S		S		S				5,88	S17	4,88
1621	#PRM# Moulding sills p/scout nero satinato Dx											
0362	Shell rearview mirror ext. primer Dx	M		M		M	0,50					
1945	#PRM# Rear fender Dx											
	Tappetino	S		S		S				50,00	S17	41,50

TOTAL TIMES	SR	LA	VE	ME	TOTAL SPARE PARTS
	3,40	1,30	6,20	0,00	287,46

DOUBLE LAYER SUPPLEMENT HOURS 15 %	FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS	ADDITIONAL HOURS FOR PAINTING	TOTAL ADDITIONAL HOURS	TOTAL PAINTING HOURS
0,93	0,71	1,60	3,24	9,44

NOTE

Right front tire - Goodyear - 225/45/18 - Summer - 5 mm
Left front tire - Goodyear - 225/45/18 - Summer - 5 mm
Right rear tire - Goodyear - 225/45/18 - Summer - 5 mm
Left rear tire - Goodyear - 225/45/18 - Summer - 5 mm
Pneumatico sapre - Kumho - 205/60/16 - Summer - 6 mm
Periodical inspection on deadline nel mese , Cdc copia compliant , Appraised in clear weather

SPARE PARTS	287,46
MATER. CONSUMPTION HOURS 9,44 €/HOUR 12,00	113,28
USE TEMPLATES	0,00
WASTING DISPOSAL	12,44
LABOR CARR. HOURS 14,14 €/HOUR 45,00	636,30
LABOR MECH. HOURS 0,00 €/HOUR 45,00	0,00
TAXABLE	1049,48
VAT	230,89
TOTAL	1280,37

EXPERT CODE	SIGNATURE	ROLE NUMBER	STOP TECHNICIAN DAYS	SHEET
176		0000	2	1

Legend
Ff: forfait Prm: reminder De: lack of execution Gr: hail Mac: stained Nu: normal wear Srg: stickers