DEKRA

Via Fratelli Gracchi 27
20092 Cinisello Balsamo (MI)
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

| DATA PERIZIA | LOCALITA' |
|---|---|
| 10/11/2026 | LOZZA SPA , Via Campi Spini 7, 24127, BERGAMO (BG) |

| VEICOLO (MARCA - MODELLO - VERSIONE) | TARGA | TELAIO | 1^ IMMATRICOLAZ. |
|---|---|---|---|
| VOLKSWAGEN GOLF 2.0 TDI SCR 85kW Life DSG Hatchback 5-door (Euro 6.2) | GL395PW | WVWZZZCDZNW218531 | 06/10/2022 |

| KM. | COLORE. | TIPO SMALTO |
|---|---|---|
| 133136 | Reflex Silver | METALL/DOPPIO |

| CODICE PARTE | VOCI DI DANNO<br>LISTINO RICAMBI AGGIORNATO AL | SR | | LA | | VE | | ME | | PREZZO LISTINO | DCMS % | RICAMBI IVA esclusa |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Diff. | TEMPO | Diff. | TEMPO | Diff. | TEMPO | Diff. | TEMPO | | | |
| | #PRM# Disco ruota posteriore dx danneggiato | | | | | | | | | | | |
| | #PRM# Parabrezza | | | | | | | | | | | |
| | Revisione ministeriale | | | | | | | | | 64,77 | | 64,77 |
| 0556 | Cofano ant. | L | 0,20 | | | L | 1,35 | | | | | |
| 1992 | Paraurti post. | L | 1,00 | L | | L | 2,40 | | | | | |
| 1992 | Scomposizione paraurti | | 1,10 | | | | | | | | | |
| 0362 | #PRM# Calotta retrovisore est. primer DX | | | | | | | | | | | |

| TOTALE TEMPI | SR | LA | VE | ME | TOTALE RICAMBI |
|---|---|---|---|---|---|
| | 2,30 | 0,00 | 3,75 | 0,00 | 64,77 |

| ORE SUPPLEMENTO DOPPIO STRATO 15 % | ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE | ORE AGGIUNTIVE PER VERNICIATURA | TOTALE ORE SUPPLEMENTARI | TOTALE ORE VERNICIATURA |
|---|---|---|---|---|
| 0,56 | 0,43 | 1,60 | 2,59 | 6,34 |

NOTE

Pneumatico ant dx - Goodyear - 205/55/16 - estivo - 6.4 mm
Pneumatico ant sx - Goodyear - 205/55/16 - estivo - 6.5 mm
Pneumatico post dx - Goodyear - 205/55/16 - estivo - 5.7 mm
Pneumatico post sx - Goodyear - 205/55/16 - estivo - 6.3 mm
Pneumatico scorta - Nexen - 205/55/16 - estivo - 7 mm
Veicolo mal stoccato

| | |
|---|---|
| RICAMBI | 64,77 |
| MATER. DI CONSUMO<br>ORE 6,34 €/ORA 12,00 | 76,08 |
| USO DIME | 0,00 |
| SMALTIMENTO RIFIUTI | 6,36 |
| MANODOPERA CARR.<br>ORE 8,64 €/ORA 45,00 | 388,80 |
| MANODOPERA MECC.<br>ORE 0,00 €/ORA 45,00 | 0,00 |
| **IMPONIBILE** | 536,01 |
| IVA | 117,92 |
| TOTALE COMPLESSIVO | 653,93 |

| CODICE PERITO | FIRMA | RUOLO N. | FERMO TECNICO GIORNI | FOGLIO |
|---|---|---|---|---|
| 25 | | 0000 | 2 | 1 |

Legenda
FF:Forfait PRM:Promemoria DE:Difetto esecuzione GR:Grandine MAC:Macchiato NU:Normale usura SRG:Adesivi

DEKRA

Via Fratelli Gracchi 27
20092 Cinisello Balsamo (MI)
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

| APPRAISAL DATE | LOCATION' |
|---|---|
| 10/11/2026 | LOZZA SPA , Via Campi Spini 7, 24127, BERGAMO (BG) |

| VEHICLE (BRAND - MODEL - VERSION) | PLATE | CHASSIS | 1st REGISTRATION. |
|---|---|---|---|
| VOLKSWAGEN GOLF 2.0 TDI SCR 85kW Life DSG Hatchback 5-door (Euro 6.2) | GL395PW | WVWZZZCDZNW218531 | 06/10/2022 |

| KM. | COLOR. | ENAMEL TYPE |
|---|---|---|
| 133136 | Reflex silver | Metall/doppio |

| PART CODE | ITEMS OF DAMAGE<br>SPARE PARTS LIST UPDATED TO | SR | | LA | | VE | | ME | | PRICE LIST | DCMS SPARE PARTS % VAT excluded | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Diff. | TIME | Diff | TIME | Diff. | TIME | Diff. | TIME | | | |
| | #PRM# Right rear wheel damaged | | | | | | | | | | | |
| | #PRM# Windscreen | | | | | | | | | | | |
| | Periodic technical inspection | | | | | | | | | 64,77 | | 64,77 |
| 0556 | Front lid | L | 0,20 | | | L | 1,35 | | | | | |
| 1992 | Rear bumper | L | 1,00 | L | | L | 2,40 | | | | | |
| 1992 | Bumper dismantling | | 1,10 | | | | | | | | | |
| 0362 | #PRM# Shell rearview mirror ext. primer Dx | | | | | | | | | | | |

| TOTAL TIMES | SR | LA | VE | ME | TOTAL SPARE PARTS |
|---|---|---|---|---|---|
| | 2,30 | 0,00 | 3,75 | 0,00 | 64,77 |

| DOUBLE LAYER SUPPLEMENT HOURS 15 % | FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS | ADDITIONAL HOURS FOR PAINTING | TOTAL ADDITIONAL HOURS | TOTAL PAINTING HOURS |
|---|---|---|---|---|
| 0,56 | 0,43 | 1,60 | 2,59 | 6,34 |

NOTE

Right front tire - Goodyear - 205/55/16 - Summer - 6.4 mm
Left front tire - Goodyear - 205/55/16 - Summer - 6.5 mm
Right rear tire - Goodyear - 205/55/16 - Summer - 5.7 mm
Left rear tire - Goodyear - 205/55/16 - Summer - 6.3 mm
Pneumatico sapre - Nexen - 205/55/16 - Summer - 7 mm
Badly stored vehicle

| | |
|---|---|
| SPARE PARTS | 64,77 |
| MATER. CONSUMPTION HOURS 6,34 €/HOUR 12,00 | 76,08 |
| USE TEMPLATES | 0,00 |
| WASTING DISPOSAL | 6,36 |
| LABOR CARR. HOURS 8,64 €/HOUR 45,00 | 388,80 |
| LABOR MECH. HOURS 0,00 €/HOUR 45,00 | 0,00 |
| **TAXABLE** | 536,01 |
| VAT | 117,92 |
| TOTAL | 653,93 |

| EXPERT CODE | SIGNATURE | ROLE NUMBER | STOP TECHNICIAN DAYS | SHEET |
|---|---|---|---|---|
| 25 | | 0000 | 2 | 1 |

Legend
Ff: forfait Prm: reminder De: lack of execution Gr: hail Mac: stained Nu: normal wear Srg: stickers